



# Vehicle History Report



2023-06-14

## AUDI R8

Located in: **Netherlands**

Vehicle reference:

**WUAZZZ423DN000518**Body type: **Coupe**Color: **black**Gearbox type: **Automatic**Drive: **AWD**Fuel type: **Petrol**Engine size: **4163 cm3**Engine power: **316 kW / 430 hp**CO2 emissions in mixed driving: **289 g/km**

Damage



Number of odometer readings: 4



Number of inspection records: 3



Number of service records: 5



Total number of records: 24



### Quick Check

#### Mileage judgement

RDW cannot judge the odometer status of this vehicle. There is not enough information available for a reliable judgement.

No judgement

#### Structural Damage

No structural damage reported to CARFAX.

No issues reported

#### Inspections

No issues reported, no inspection due in the next 6 months

No issues reported

#### Recalls

There are currently no recalls reported to CARFAX.

No issues reported

#### Import

Not a private import

No issues reported

#### Taxi

Not used as taxi

No issues reported

#### Damage

This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.

Damage


This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

## Damage Overview

2021-05-05 Damage reported in Netherlands



## Mileage Check



### No issues indicated

The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

## Highlights

### Users in Netherlands



Number of users: 5

Private users: 1  
Non-private users: 4

### Vehicle age



First registration date: 2014-11-03

### Inspections



Latest inspection:  
2022-10-28

## History information

Date	Mileage	Event
2014-11-03		Registered in Netherlands New owner reported Commercial usage reported in Netherlands

Date	Mileage	Event
2015-04-13		New owner reported Commercial usage reported in Netherlands
2015-06-13	17,592 km	Offered for sale on AutoTrack <a href="http://www.autotrack.nl">www.autotrack.nl</a>
2015-07-01		Offered for sale on AutoTrack <a href="http://www.autotrack.nl">www.autotrack.nl</a>
2015-07-13		New owner reported Owner type: dealer For sale usage reported in Netherlands
2015-08-25		New owner reported Owner type: dealer For sale usage reported in Netherlands
2015-10-29		New owner reported Commercial usage reported in Netherlands
2018-06-08		New owner reported Owner type: private individual Private usage reported in Netherlands
2020-08-26		Inspected in Netherlands Inspection passed
2021-01-05		New owner reported Owner type: dealer For sale usage reported in Netherlands
2021-01-08		New owner reported Owner type: dealer For sale usage reported in Netherlands
2021-01-11		New owner reported Owner type: dealer For sale usage reported in Netherlands
2021-04-24		New owner reported Owner type: dealer For sale usage reported in Netherlands
2021-05-05	41,105 km	Damage repaired ■ Bodywork paint finish

Date	Mileage	Event
2021-06-12		New owner reported Owner type: dealer For sale usage reported in Netherlands
2021-09-15		Maintenance performed ■ Battery replacement
2021-11-23		Vehicle insured
2022-03-02		Workshop visited
2022-08-23	41,500 km	Workshop visited
2022-10-19		Inspected in Netherlands Inspection passed
2022-10-20		New owner reported Owner type: dealer Commercial usage reported in Netherlands
2022-10-28		Inspected in Netherlands Inspection type: regular
2022-10-28	42,604 km	Maintenance performed ■ Brake fluid replacement
2022-10-29		New owner reported Owner type: dealer For sale usage reported in Netherlands

Based on data reviewed from 22 countries in Europe and North America

Technical details	
Environment and consumption	
Fuel type	Petrol
Fuel consumption in mixed driving	12.4 l/100km
CO2 emissions in mixed driving	289 g/km
EU emission standard	Euro 5
Weight	
Curb weight	1,560 kg
Max payload	325 kg
Gross vehicle weight	1,885 kg
Dimensions	
Wheelbase	2,650 mm
Other information	
European vehicle category	M1
EU standard code	E1*2001/116*0399*11
Number of doors	2
Number of seats	2

## CARFAX Glossary

### CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

### Damage

Damage can be a result of many different types of events. Examples include contact with objects (other vehicles, trees, traffic signs, road debris, etc), vandalism, fire, flood, or other weather-related events. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

### Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

### Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

**Number of records**

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

**Quick Check**

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

**Service records**

CARFAX has an extensive database of service records, including oil changes and other routine maintenance procedures. Remember to also ask the seller for service and maintenance records.

**Users**

Total number of users in a given country, registered both for private and non-private use.

**Vehicle reference**

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.