



# Vehicle History Report



2023-10-16

## PORSCHE 911

Located in: **Spain**

Vehicle reference:

**WP0ZZZ99Z3S630751**Fuel type: **Petrol**Engine size: **3596 cm3**

Number of odometer readings: 4



Number of inspection records: 5



Total number of records: 8



### Quick Check

#### Mileage

The reported odometer readings have a logical progression.

**No issues indicated**

#### Stolen

Not reported stolen

**No issues reported**

#### Identity check

Not reported scrapped

**No issues reported**

#### Import

Not a private import

**No issues reported**

#### Taxi

Not used as taxi

**No issues reported**

#### Chassis

No modification or replacement reported

**No issues reported**

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.


### Damage Overview

#### No damage reported

There has been no damage reported for this vehicle



## Mileage Check



### No issues indicated

The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

## Highlights

### Owners in Spain



Number of owners: 3

Number of transfers: 2

### Odometer

**36521**

Last reported: 2022-11-24

### Vehicle age



First registration date: 2004-07-26

### Inspections



Latest inspection:  
2022-11-24

### Emissions sticker in Spain



Emissions sticker: B

## History information

Date	Mileage	Event

Date	Mileage	Event
2004-07-26		Registered in Benicarlo, Spain New owner reported Owner type: commercial Private usage reported in Spain Located in Benicarlo, Castellon, Spain
2010-12-30		New owner reported
2013-01-14	26,826 km	Inspected in CATALUÑA, Spain Inspection type: regular Inspection failed
2013-01-17		Re-inspected in Spain Inspection type: regular Inspection passed
2016-02-08	30,340 km	Inspected in CATALUÑA, Spain Inspection type: regular Inspection passed
2019-01-29	34,770 km	Inspected in Spain Inspection type: regular Inspection passed
2022-11-24	36,521 km	Inspected in Spain Inspection type: regular Inspection passed
2023-03-03		New owner reported Owner type: commercial Private usage reported in Spain Located in S Susanna, Barcelona, Spain

Based on data reviewed from 22 countries in Europe and North America

Technical details	
Environment and consumption	
Fuel type	Petrol
EU emission standard	Euro 3
Weight	
Curb weight	1,530 kg
Max payload	315 kg
Gross vehicle weight	1,845 kg
Other information	
European vehicle category	M1
EU standard code	E13*98/14*0031*12
Number of doors	2
Number of seats	4

## CARFAX Glossary

### Emissions sticker

Emissions sticker and characteristics of the vehicles classified in the vehicles registration by DGT in regards to vehicle emissions. Soon, everyone will need a sticker because more and more cities and communities are setting up environmental zones, which are off limits to vehicles that give off high levels of harmful emissions. The authorities are employing this measure to reduce hazardous pollution in the form of fine particulate matter. To drive in such a zone, you need a valid sticker, or you need an approved exception. Otherwise you need to stay out.

### Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

### Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

### Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

### Odometer

The number of kilometers displayed on the most recent odometer reading.

### Owners

Total number of owners in a given country, registered both for private and non-private use. Not all owners actually had to use this vehicle.

### Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

**Vehicle reference**

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.