
	Number of odometer readings: 6	a constant	
	Number of inspection records: 6	100 m	
	Total number of records: 9		
Mileage The reported odometer readings have a logical progression.			
		✓ No issues reporte	
		No issues reporte	
		No issues reporte	
		No issues reported	
		No issues reporte	
		readings: 6 Number of inspection records: 6 Total number of records: 9	


No damage reported There has been no damage reported for this vehicle

 \bigcirc



No issues indicated

The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.



Date	Mileage	Event	
2006-12-20		Registered in Barcelona, Spain New owner reported Owner type: commercial Private usage reported in Spain Located in Barcelona, Barcelona, Spain	

Date	Mileage	Event		
2013-01-17	14,836 km	Inspected in CATALUÑA, Spain Inspection type: regular Inspection passed		
2014-10-30	20,643 km	Inspected in CATALUÑA, Spain Inspection type: regular Inspection passed		
2017-03-03	29,601 km	Inspected in Spain Inspection type: regular Inspection passed		
2019-02-18	29,803 km	Inspected in Spain Inspection type: regular Inspection passed		
2021-05-07	29,983 km	Inspected in Spain Inspection type: regular Inspection passed		
2021-06-04		New owner reported Owner type: commercial Private usage reported in Spain Located in S Cugat Del Valles, Barcelona, Spain		
2022-05-04	38,198 km	Inspected in Spain Inspection type: regular Inspection passed		
2022-12-30		New owner reported Owner type: commercial Private usage reported in Spain Located in Igualada, Barcelona, Spain		
Based on data reviewed from 22 countries in Europe and North America				

Technical details Environment and consumption Fuel type Petrol EU emission standard Euro 4 Weight Curb weight 1,635 kg Max payload 240 kg Gross vehicle weight 1,875 kg Other information European vehicle category M1 EU standard code E13*2001/116*0137*05 Number of doors 2 Number of seats 4

CARFAX Glossary

Emissions sticker

Emissions sticker and characteristics of the vehicles classified in the vehicles registration by DGT in regards to vehicle emissions. Soon, everyone will need a sticker because more and more cities and communities are setting up environmental zones, which are off limits to vehicles that give off high levels of harmful emissions. The authorities are employing this measure to reduce hazardous pollution in the form of fine particulate matter. To drive in such a zone, you need a valid sticker, or you need an approved exception. Otherwise you need to stay out.

Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Owners

Total number of owners in a given country, registered both for private and non-private use. Not all owners actually had to use this vehicle.

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.