CARFA✓ Vehicle History Report



FERRARI 348 tb/GTB

Located in: **Spain**Vehicle reference:

ZFFFA35S000090070

Drive: Rear
Fuel type: Petrol
Engine size: 3403 cm3
Engine power: 221 kW / 300 hp



Imported vehicle



Number of odometer readings: 5



Number of inspection records: 5



Total number of records: 12



Quick Check	
Mileage The reported odometer readings have a logical progression.	No issues indicated
Stolen Not reported stolen	No issues reported
Identity check Not reported scrapped	No issues reported
Import Vehicle imported	i Import
Taxi Not used as taxi	No issues reported
Chassis No modification or replacement reported	No issues reported


This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

Damage Overview

No damage reported

There has been no damage reported for this vehicle





No issues indicated

The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.



History information				
Date	Mileage	Event		
1991-06-13		First registration abroad		
2000-01-19		Imported to Portugal Registered in Portugal		

Date	Mileage	Event		
2007-05-14		Imported from Portugal to Spain Registered in Palma Mallorca, Spain New owner reported Owner type: private individual Private usage reported in Spain Located in Palma Mallorca, Illes Balears, Spain		
2007-07-13		Registered in Palma Mallorca, Spain New owner reported Owner type: private individual Located in Palma Mallorca, Illes Balears, Spain		
2008-04-03		New owner reported		
2014-05-16	52,570 km	Inspected in BALEARS (ILLES), Spain Inspection type: regular Inspection passed		
2019-03-13	53,575 km	Inspected in Spain Inspection type: regular Inspection passed		
2020-09-17	53,978 km	Inspected in Spain Inspection type: regular Inspection passed		
2022-08-03		New owner reported Owner type: private individual Located in Carballo, A Coruña, Spain		
2023-03-03		New owner reported Owner type: commercial Located in S Susanna, Barcelona, Spain		
2023-07-27	55,623 km	Inspected in Spain Inspection type: regular Inspection failed		
2023-08-10	55,658 km	Re-inspected in Spain Inspection type: regular Inspection passed		
Based on data reviewed from 22 countries in Europe and North America				

Technical details				
Environment and consumption				
Fuel type	Petrol			
Weight				
Curb weight	1,450 kg			
Max payload	230 kg			
Gross vehicle weight	1,680 kg			
Other information				
European vehicle category	M1			
EU standard code	B-1402			
Number of doors	2			
Number of seats	2			

CARFAX Glossary

Imported vehicle

A vehicle that has been imported from another country

Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Odometer

The number of kilometers displayed on the most recent odometer reading.

Owners

Total number of owners in a given country, registered both for private and non-private use. Not all owners actually had to use this vehicle.

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.