



Vehicle History Report



2023-10-20

ROVER MINI Hatchback

Located in: **Spain**

Vehicle reference:

SAXXNNAYNBD069951Body type: **Sedan**Drive: **Front**Fuel type: **Petrol**Engine size: **1275 cm3**Engine power: **46 kW / 63 hp**

Imported vehicle



Number of odometer readings: 3



Number of inspection records: 3



Total number of records: 7



Quick Check

Mileage

The reported odometer readings have a logical progression.

No issues indicated

Stolen

Not reported stolen

No issues reported

Identity check

Not reported scrapped

No issues reported

Import

Vehicle imported

Import

Taxi

Not used as taxi

No issues reported

Chassis

No modification or replacement reported

No issues reported

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

Damage Overview


No damage reported

There has been no damage reported for this vehicle



Mileage Check

Date | Mileage
2013-12-17 | **41,422 km**



No issues indicated

The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

Highlights

Owners in Spain



Number of owners: 5

Number of transfers: 4

*Not all ownership changes are visible in the detailed history

Vehicle age



First registration date: 1993-09-14

History information

Date	Mileage	Event
1993-09-14		First registration abroad

Date	Mileage	Event
2008-11-26		Imported to Spain Registered in Ripollet, Spain New owner reported Owner type: private individual Private usage reported in Spain Located in Ripollet, Barcelona, Spain
2008-12-15		New owner reported
2011-02-18		New owner reported
2013-12-17	41,422 km	Inspected in CATALUÑA, Spain
2015-01-21	42,743 km	Inspected in CATALUÑA, Spain
2016-01-19	47,384 km	Inspected in CATALUÑA, Spain
Based on data reviewed from 22 countries in Europe and North America		

Technical details

Environment and consumption

Fuel type **Petrol**

Weight

Curb weight **685 kg**

Max payload **365 kg**

Gross vehicle weight **1,050 kg**

Other information

European vehicle category **M1**

EU standard code **E11*93/81*0045*00**

Number of doors **2**

Number of seats **4**

CARFAX Glossary

Imported vehicle

A vehicle that has been imported from another country

Number of inspection records

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Owners

Total number of owners in a given country, registered both for private and non-private use. Not all owners actually had to use this vehicle.

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.