CARFAX Vehicle History Report



ALPINE A110 II

Located in: Spain Vehicle reference:

VFAAEFD0467779324

Body type: Coupe Gearbox type: Automatic Drive: Rear Fuel type: Petrol Engine size: 1798 cm3 Engine power: 185 kW / 252 hp

CO2 emissions in mixed driving: 153 g/km



Leased vehicle



Total number of records:



Quick Check Mileage Currently, no odometer readings have been reported to CARFAX for this No issues indicated vehicle. Stolen No issues reported Not reported stolen **Identity check** No issues reported Not reported scrapped **Import** No issues reported Not a private import Taxi No issues reported Not used as taxi Chassis No issues reported No modification or replacement reported

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

Extra information

Administrative status in Spain

Financial charges, taxes, and administrative situation status

Check

Damage Overview

No damage reported

There has been no damage reported for this vehicle



13/12/2023, 14:34 1 sur 4

Mileage Check

No mileages reported yet

Currently, no odometer readings have been reported to CARFAX for this vehicle. Ask the seller for documented odometer readings, e.g. vehicle documents or service invoices to verify the odometer reading listed in the offer. Calculate the average kilometers driven per year and critically question whether the current odometer reading is correct.

Highlights

Owners in Spain

Vehicle age



Number of owners: 2



Number of transfers: 1

First registration date: 2021-11-17

History information		
Date	Event	
2021-11-17	Leasing reported Registered in Moralzarzal, Spain New owner reported Owner type: commercial Private usage reported in Spain Located in Moralzarzal, Madrid, Spain	
2022-10-17	New owner reported Owner type: commercial Private usage reported in Spain Located in Logroño, La Rioja, Spain	

2 sur 4 13/12/2023, 14:34

Technical details			
Environment and consumption			
Fuel type	Petrol		
CO2 emissions in mixed driving	153 g/km		
EU emission standard	Euro 6		
Weight			
Curb weight	1,099 kg		
Max payload	225 kg		
Gross vehicle weight	1,324 kg		
Dimensions			
Wheelbase	2,420 mm		
Other information			
European vehicle category	M1		
EU standard code	e2*2007/46*0612*13		
Number of doors	3		
Number of seats	2		

CARFAX Glossary

CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

Leased vehicle

When someone leases a car from a dealer, the dealer actually sells the vehicle to a leasing company, which can be an independent car dealer or a car manufacturer

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Owners

Total number of owners in a given country, registered both for private and non-private use. Not all owners actually had to use this vehicle.

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

3 sur 4 13/12/2023, 14:34

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

4 sur 4