



Vehicle History Report



2024-01-26

ABARTH 500E Hatchback

Located in: **Spain**

Vehicle reference:

ZFA31200000612418

Body type: **Hatchback**

Gearbox type: **Manual**

Drive: **Front**

Fuel type: **Petrol**

Engine size: **1368 cm3**

Engine power: **132 kW / 179 hp**

CO2 emissions in mixed driving: **154 g/km**



Imported vehicle



Number of odometer readings: 4



Number of inspection records: 4



Total number of records: 9

Report created on:

2024-01-26 at 14:51:57 UTC



Scan QR code for [current version](#)
(available until: 2024-02-25)

Quick Check

Mileage

The reported odometer readings have a logical progression.



No issues indicated

Stolen

Not reported stolen



No issues reported

Identity check

Not reported scrapped



No issues reported

Import

Vehicle imported from Italy



Import

Taxi

Not used as taxi



No issues reported

Chassis

No modification or replacement reported



No issues reported

Damage

No damage reported to CARFAX



No issues reported

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

Extra information

Administrative status in Spain

Financial charges, taxes, and administrative situation status

[Check](#)

Damage Overview

No damage reported

There has been no damage reported for this vehicle



Mileage Check

Date
2023-12-28 | Mileage
6,649 km



No issues indicated

The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

Highlights

Owners in Spain



Number of owners: 2

Number of transfers: 1

Odometer

6645

Last reported: 2023-12-28

Vehicle age

years: **13** | months: **2**

First registration date: 2010-10-27

Inspections



Latest inspection:
2023-12-28

Emissions sticker in Spain



Emissions sticker: C

History information

Date	Mileage	Event
2010-10-27		Registered in Italy
2010-11-22		De-registered in Italy

Date	Mileage	Event
2011-04-20		Imported from Italy to Spain Registered in Barcelona, Spain New owner reported Owner type: private individual Private usage reported in Spain Located in Barcelona, Barcelona, Spain
2017-03-24	6,144 km	Inspected in Spain Inspection type: regular Inspection passed
2019-03-22	6,387 km	Inspected in Spain Inspection type: regular Inspection passed
2021-04-13		Inspected in Spain Inspection type: regular Inspection passed
2023-12-28	6,645 km	Inspected in Spain Inspection type: regular Inspection failed
2023-12-28	6,649 km	Re-inspected in Spain Inspection type: regular Inspection passed
2024-01-10		New owner reported Owner type: commercial Located in Tordera, Barcelona, Spain

Based on data reviewed from 22 countries in Europe and North America

Technical details	
Environment and consumption	
Fuel type	Petrol
CO2 emissions in mixed driving	154 g/km
EU emission standard	Euro 4
Weight	
Curb weight	1,145 kg
Max payload	315 kg
Gross vehicle weight	1,460 kg
Other information	
European vehicle category	M1
Number of doors	3
Number of seats	4

CARFAX Glossary

CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

Emissions sticker

Emissions sticker and characteristics of the vehicles classified in the vehicles registration by DGT in regards to vehicle emissions. Soon, everyone will need a sticker because more and more cities and communities are setting up environmental zones, which are off limits to vehicles that give off high levels of harmful emissions. The authorities are employing this measure to reduce hazardous pollution in the form of fine particulate matter. To drive in such a zone, you need a valid sticker, or you need an approved exception. Otherwise you need to stay out.

Imported vehicle

A vehicle that has been imported from another country

Number of inspection records

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Odometer

The number of kilometers displayed on the most recent odometer reading.

Owners

Total number of owners in a given country, registered both for private and non-private use. Not all owners actually had to use this vehicle.

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.